


# INSTALLATION AND OWNER'S MANUAL

**Side Illumination Lights** Z5150

for use with K 1200 LT

Read these instructions carefully and thoroughly before beginning work.

Before installing the accessory, carefully consider whether one possesses the necessary technical skills and workshop tools to complete the installation properly. Otherwise, any BMW Motorcycle Retailer will be glad to install this accessory.



- 1. Torx Key Wrench, T25
- 2. Hex Key Wrench, 3mm
- 3. Hex Key Wrench, 4mm
- 4. Phillips Screwdriver, #2
- 5. x-acto blade or other sharp blade.
- 6. Scissors
- 7. Adhesive Tape (masking or cellophane)
- 8. Brad Point Drill Bit, 7/16" (11mm) This works best, if not available, use a Center Punch To Start the Hole and a Spade Drill.
- 9. Hole Saw, 2 ½" or 65mm
- 10. Electric Hand Drill
- 11. Round File or Hand Grinder with Round Tip
- 12. 10mm Wrench (from Motorcycle Tool Kit or other)

#### **Parts List**

Qty.	Part No.	<u>Description</u>
1	90-910510-000	Side Illumination Light, Left
1	90-910511-000	Side Illumination Light, Right
1	10-117744-000	Template, Left
1	10-117745-000	Template, right

## Bag#410

6	51-516511-000 Screw, Button Head, M5 x 10
6	44-443207-000 O-ring, .350 ID x .250 thick
6	49-490170-000 Clamping Washer
2	75-762410-000 Gasket 75150 Side Illumination Lights


# Bag#411


1 80-830110-000 Wire Loom, Power, Z5150 1 80-813801-000 Relay

10 44-448723-000 Tie Wrap

## Bag#412

- 1 80-814650-000 Switch Assembly
- 2 51-515230-000 Screw, Hex Socket, M5 x 30
- 1 Scotchlok Connector







Special notes and coutionary measures which can prevent damage to the motorcycle.



Tips for facilitation of operation, control and adjustment, as well as maintenance work.

ZTechnik PO Box Maywood, IL 60153-0158 USA

708-343-0400 / Fax: 708-343-0625 / www.Z Technik.com / e mail: info@Z Technik.com

©2003 National Cycle, Inc.

Page 1 of 8

10-117734-000 04/03



Figure 1




Figure 2



Figure 3 Center Spoiler Left Spoiler

#### **PREPARATION**



Note: Left and Right are determined from the rider's position.

Position the motorcycle securely on its main stand or a work stand.



**Note:** Retain all the fasteners for the body panels, all these fasteners will be reused. Individual bags to hold fasteners into separate groups will be helpful!

1. Remove the upper, left side, handle bar cover. (3mm Hex Wrench) Figure 1.





- 2. Remove the Rocker Panel Moldings, with their covers, from both sides of the motorcycle (black and chrome tip-over guards.) (3mm Hex Wrench)
  Figure 2.
- 3. Remove the Center, Left and Right Engine Spoilers (lower front and side panels). (Use the T25 Torx for the 6 front screws and 3mm Hex for the underside screws) Figure 3.



Note: The reverse Knob must be removed

ZTechnik PO Box Maywood, IL 60153-0158 USA

708-343-0400 / Fax: 708-343-0625 / www.Z Technik.com / e mail: info@Z Technik.com

©2003 National Cycle, Inc.

Page 2 of 8

10-117734-000 4/03



**4.** Remove the left side Covering with Guide Plate (clear plastic wind flap and its mount). **(T25 Torx) Figure 4.** 

Figure 4





Figure 5



**6.** Remove the left side Trim Panel (main body panel on left.) (T25 Torx)



**Note:** To remove the main body panel these items will be removed:

- **A.** 1 screw from light lens, pop lens off, remove 2 screws around light. (Phillips Screw Driver, T25 Torx) **Figure 5**.
- **B.** 2 screws from panel below glove compart ment and 1 screw from the lower left. (3mm Hex) Figure 6.

**ZTechnik** PO Box Maywood, IL 60153-0158 USA 708-343-0400 / Fax: 708-343-0625 / www.Z Technik.com / e mail: info@Z Technik.com e, Inc. Page 3 of 8 10-117734-000 4/03

©2003 National Cycle, Inc.



Figure 7



Figure 8



Long Green Wire routes down through steering area to the inside of fairing.

Short Green Wire will attach to White / Yellow Stripe Wire. Step #5.

#### INSTALLATION OF SWITCH ASSEMBLY

- 1. From beneath the left side handlebar switch assembly, remove the screws that hold the radio remote control. These 2 screws will not be re-used. (3mmHex) Figure 7.
- **2.** Position the supplied Switch Assembly so the collars insert where the screws from the previous step were located.
- 3. Thread in the M5  $\times$  30 screws and tighten. (4mm Hex) Figure 8.

- **4.** Route the Switch wires into the lower handlebar cover with the longer green wire going through the steering area into the inside of the fairing. **Figure 9.**
- 5. There are four wire looms inside the handlebar cover. The largest loom must be carefully cut open where the handlebar increases diameter. (Sharp Knife) Figure 10.
- **6.** Carefully lift out the White / Yellow Stripe Wire. **Figure 11.**

Using the "Scotchlok" connector, attach the SHORT GREEN WIRE from the Switch to the WHITE WITH YELLOW STRIPE wire inside the loom. (Pliers) Figure 12.




Figure 9

ZTechnik PO Box Maywood, IL 60153-0158 USA

708-343-0400 / Fax: 708-343-0625 / www.Z Technik.com / e mail: info@Z Technik.com

©2003 National Cycle, Inc.

Page 4 of 8

10-117734-000 4/03




Figure 13



Figure 14

## **CONNECTION OF RELAY**

**1.** Attach the Main Power Wire Loom to the Relay. **Figure 13.** 

Two BROWN wires connector to spade #85

Green Wire connector that goes to white connector blocks to spade #30

Green Wire that goes to battery ring terminals to spade #87.

Switch Assembly Wire from Handlebar Switch to spade #86 **Figure 14**.


©2003 National Cycle, Inc.

Page 5 of 8

10-117734-000 4/03



Figure 15



#### **Power Loom**

- **1.** Position the Main Power Wire Loom (the end with two ring terminals) to run from the relay to the battery along the top of the fuel tank. **Figure 15.**
- 2. At the front of the fuel tank, run the loom to the center of the motorcycle between the forks and above the fairing support. The two leads with the white connector blocks will hang down from either side of the fairing support. Figure 16.
- **3. Connect the Power Loom to the battery.** The red wire goes to the positive terminal on the battery. The brown wire goes to the negative terminal on the battery. (10mm Wrench)

## **CHECK OPERATION OF LIGHTS**

- **1.** Connect the Side Illumination Lights to the connectors on the Power Loom.
- **2.** Turn the ignition key to "on" and verify the operation of the side Illumination Lights. If they do not function, examine the installation by following the installation instructions thoroughly.


## SECURE WIRES, RE-INSTALL PARTS

- **1.** Tuck the Loom between the fuel tank and the top body panels. Secure the Loom along the frame with Tiewraps.
- 2. Secure the Relay, using tie-wraps, to the fairing support so it cannot be touched by the fork when turning. Secure the Loom and the Switch wire, to the fairing support, again, make certain the Loom will not touch the fork when turning.
- 3. The covers may now be re-assembled to the handle-
- **4.** The left side Trim Panel and the Covering with Guide Plate should be re-installed now.

Be sure to secure Power Loom and any extra length of wire well.
Use cautionary measures to assure that

the Power Loom is away from the engine, exhaust, front wheel and forks. Secure any extra length with tie wraps, then secure to fairing support.

ZTechnik PO Box Maywood, IL 60153-0158 USA




# INSTALLATION OF THE SIDE ILLUMINATION LIGHTS

- **1.** Carefully cut the Templates along the indicated lines. **(Scissors)**
- 2. Tape the Templates in place on the left and right side Engine Spoiler panels. Make sure to align the Templates at the critical lines. **Figure 17.**



Note: The 3/8" space required at Point A.

- **3.** Using the Brad Point Drill (or Center Punch) mark the centers of the holes, as indicated on the Templates. **Figure 18.**
- 4. Remove the Templates. Figure 19.
- **5.** Using the 7/16" Brad Point Drill Bit and the Electric Drill, drill three holes into each Spoiler side. **Figure 20.**
- **6.** Using the Hole Saw and Electric Drill, drill the large holes. Use a low drill speed. Make sure the saw does not wander. **Figure 21.**






Figure 21

ZTechnik PO Box Maywood, IL 60153-0158 USA






Figure 23



**7.** Test fit the Side Illumination Light on the Engine Spoiler. From the inside mark where more material needs to be removed. Use the Round File (or grinder) to adjust the holes so the Side Illumination Light fits well. Figure 22.

Note: Remove small amounts of material at a time. Re-check fit and adjust.

## **INSTALL FASTENERS TO LIGHT**

- 1. Place a gasket on the outside surface of the Engine Spoiler and position the Light Assembly.
- 2. On the inside surface of the Engine Spoiler place an O-ring on each screw boss, then a Clamping Washer and a Button Head Screw. Figure 23. The O-ring needs to compress to start screw.
- 3. Tighten securely. (3mm Hex)

## **CONNECT LIGHTS, RE-INSTALL BODY PANELS**

- 1. Connect the Side Illumination Lights to the connectors on the Power Loom. Make sure the wires are safely positioned inside the fairing and away from the exhaust system.
- 2. Install left and right sides of the Engine Spoiler.
- 3. Install the center of the Engine Spoiler.

## **MAINTENANCE**

The Side Illumination Lights are coated aluminum. Do not use chrome or metal polish. Allow the lights to cool, then wash as you would the rest of the motorcycle.

To replace a bulb, remove the affected side of the Engine Spoiler. Unscrew the cap inside the Side Illumination Light casting. This will give access to the bulb. Replace the bulb and re-assemble in reverse order of disassembly.

Side Illumination Lamp Assembly Replacement: Part No. 90-901400-000

ZTechnik PO Box Maywood, IL 60153-0158 USA